

Unit #	Completed	WO	HOUR	MILES	Task Note	Task	Notes	Total Cost
003	4/29/2024 10:53	2050	9521 Hours	77059 Miles		CAD		\$52.80
003	4/29/2024 10:53	2050	9521 Hours	77059 Miles		Electrical		\$80.02
003	4/3/2024 13:23	2013	9456 Hours	76191 Miles	Found dirt under pedal. Cleaned out and lubed pedal	Brakes		\$15.00
003	2/29/2024 16:06	1968	9398 Hours	75209 Miles	Matt adjusted the clutch brake and the clutch pedal free play. Jake verified it was completed proper	Drivetrain		\$60.00
003	2/7/2024 9:05	1952	9376 Hours	74924 Miles		Annual Inspection		\$60.00
003	2/7/2024 9:05	1952	9376 Hours	74924 Miles	Found two torque rod bushings blown out and the main walking arm bushings slid over. Unbolted walking/trailing arms replaced bushings and realigned arms.	Suspension		\$139.50
003	2/7/2024 9:05	1952	9376 Hours	74924 Miles	Matt replaced an exhaust section that was leaking. replaced missing bolts in a crossmember, identified sway bar bushings and torque arm bushings that needed replaced.	Identify and record any issues, dot or otherwise.		\$60.00
003	11/30/2023 7:51	1909	9342 Hours	74362 Miles	Performed lube service. Changed engine oil and filter, fuel filters, greased, adjusted brakes etc all per inspection sheet. Rear torque rods over rear axle all 4 bushings going out, engine oil pan leaking. 9342 hours. 74362 miles.	Lube Service		\$183.91
003	11/30/2023 7:51	1909	9342 Hours	74362 Miles	Replaced serpentine belt tensioner. Part not yet in inventory. CAT PN# 1900649	Engine		\$301.99
003	11/30/2023 7:51	1909	9342 Hours	74362 Miles	Replaced both cad system steer motor hyd. Lines.	CAD		\$40.00
003	11/6/2023 11:16	1881	9216 Hours	72299 Miles	Replaced air line between bugle line and air dryer.	Air System		\$48.00
003	10/11/2023 6:59	1872	9103 Hours	70564 Miles	Replaced R-12 relay valve.	Air System		\$52.79
003	10/2/2023 15:58	1856	9033 Hours	69623 Miles	Did an oil change and grease. And put a deflector in the slinger chain box.	Lube Service		\$236.66
003	10/2/2023 15:58	1856	9033 Hours	69623 Miles		Replace leaking agitator cylinder		\$0.00
003	10/2/2023 15:58	1856	9033 Hours	69623 Miles	bert replaced feed motor	Repair leak on feed motor		\$465.62
003	8/22/2023 9:27	1814	8805 Hours	65995 Miles	Found out that the fan box was full dirt. Blow out the dirt and fan started to work better.	AC		\$16.00
003	8/22/2023 9:27	1814	8805 Hours	65995 Miles	Pulled off the slinger. Got the leaking pipe out, had to clean out all the Sauter in the pipe fitting. Welded the fitting back on and pressure tested it. Put the pipe back on. And put a new slinger belt on.	CAD		\$930.00
003	8/2/2023 6:57	1792	8717 Hours	64542 Miles	Performed service. Changed engine oil and filter, fuel filters, greased, checked boxes etc all per inspection sheet. 8717 hours. 64542 miles.	Lube Service		\$587.52
003	8/2/2023 6:57	1792	8717 Hours	64542 Miles	Found on the rear drive that both of torque arm bushings need to be replaced. Had to cut one off the bolts to get a arm out. Put new bushing in and put the arms back on. Welded a crack on one of the suspension bag mounts.	Suspension		\$240.00
003	8/2/2023 6:57	1792	8717 Hours	64542 Miles	Replaced serpentine belt	Engine		\$97.50
003	6/6/2023 8:02	1737	8393 Hours	59196 Miles	Replaced first u joint off of transmission. 59,136 hours. 8392 hours	Drivetrain		\$96.05
003	6/6/2023 8:02	1737	8393 Hours	59196 Miles	Changed engine oil and filter, fuel filters and air filter. Checked boxes, adjusted brakes, greased etc all per inspection sheet. 59196 miles. 8392 hours	Lube Service		\$472.37
003	5/16/2023 10:51	1712	8233 Hours	56334 Miles	Replaced 4 wheel bearings and one wheel with used wheel with new bearings already installed. Replaced belt. 8233 hours. 56334 miles	CAD		\$200.08
003	5/16/2023 10:51	1712	8233 Hours	56334 Miles		Exhaust		\$79.95
003	4/5/2023 10:26	1676	8080 Hours	53854 Miles	PERFORMED LUBE SERVICE. FOUND AIR FILTER STILL IN GOOD CONDITION.	Lube Service		\$170.81
003	2/28/2023 10:01	1629	7923 Hours	52039 Miles	Swing motor found to be leaking. Replaced swing motor, swing chain and pivot chain. Lubed and adjusted	CAD		\$484.61
003	1/30/2023 9:25	1620	7923 Hours	52039 Miles		Annual Inspection		\$35.00
003	1/30/2023 9:25	1620	7923 Hours	52039 Miles	Put in a new block heater.	Engine		\$185.05
003	1/30/2023 9:25	1620	7923 Hours	52039 Miles	Replaced cab lights and rear box 3 middle marker lights with LED.	Electrical		\$56.64
003	1/12/2023 9:15	1615	7923 Hours	52039 Miles	Inspected drive axle brakes and found all 4 slacks to be worn out and one brake can damaged. Replaced all 4 slacks and brake can with new. 7932 hours. 52039 miles.	Brakes		\$409.75
003	12/6/2022 15:12	1580	7480 Hours	45442 Miles	Motor and axle shaft for the super shield had spun the input shaft. So had to replace the motor and the axle shaft	CAD		\$30.00
003	12/6/2022 15:11	1572	7480 Hours	45442 Miles	Replace the drive sprocket and taper lock on the feed belt. And had to replace the switch for the hydraulic cooling fans.	CAD		\$65.38
003	11/15/2022 14:26	1562	7480 Hours	45442 Miles	Replaced front differential lock piston Cap. Part not yet in stock, #129573ETN,	Air System		\$41.13
003	11/15/2022 14:26	1562	7480 Hours	45442 Miles	Replaced inner ball joint/tie rod on pivot cylinder. Part not yet in stock, Dayton #310-228 RH thread. 11/11/22	CAD		\$206.95
003	10/25/2022 15:18	1543	7480 Hours	45442 Miles	Had to put a new key and tapered lock bushing on the feed belt motor	CAD		\$15.00

003	10/21/2022 9:57	1547	7480 Hours	45442 Miles	Tail pulley wore through, found that gates were bent. Installed new gate guides, installed gate cover plates. Straightened gates, and installed 2 new gate cylinders. Installed new feed belt and tracked system.	CAD		\$1,271.98
003	10/21/2022 9:57	1547	7480 Hours	45442 Miles	Changed engine oil and filter, fuel filters. Oil filter stock out. 7769 hours	Service		\$193.58
003	10/21/2022 9:57	1547	7480 Hours	45442 Miles	Performed pm and service. Changed engine oil and filter, both fuel filters, greased, adjusted brakes etc per inspection sheet. Through inspection found leaky power steering fitting that was loose. Also found lower radiator hose leaking. 7769 hours	Inspection		\$0.00
003	10/21/2022 9:57	1547	7480 Hours	45442 Miles	Found loose and leaking power steering fitting. Replaced O ring and reinstalled. 7769 hours	Steering		\$0.00
003	10/21/2022 9:57	1547	7480 Hours	45442 Miles	Leaking lower radiator hose. Replaced upper 2 1/2 inch hose. 7769 hours	Engine		\$15.00
003	8/26/2022 8:25	1515	7326 Hours	43272 Miles	Replaced blown air bag on drive axle.	Suspension		\$32.50
003	8/26/2022 8:25	1515	7326 Hours	43272 Miles	Dalton replaced faulty headlight.	Safety Devices		\$18.04
003	8/18/2022 13:35	1507	7326 Hours	43272 Miles	Had to grind out and weld cracks on the air bag bracket on the rear diff housing. Found that there was a bad torque rod bushing. Replace both bushings. Replace both frame shocks on the driver side	Suspension		\$619.90
003	8/18/2022 13:35	1507	7326 Hours	43272 Miles	Changed engine oil and filter, fuel filters and air filter. 44,130 mi. 7398 hours.	Service		\$111.94
003	8/18/2022 13:35	1507	7326 Hours	43272 Miles	Performed Pm and service. Changed engine oil and filter, fuel filters and air filter. Greased, adjusted brakes, checked boxes etc per inspection sheet. Through inspection found one torque rod bushing worn so removed and replaced both bushings. Grinded and welded shock absorber mounts and replaced both driver side shocks. 44,130 mi. 7398 hrs.	Inspection		\$45.00
003	8/9/2022 9:28	1503	7326 Hours	43272 Miles	Found transmitter and reciever not connecting. Found broken wire on rf module inside transmitter, also found power issue in transmitter coding board. Sent off transmitter and reciever to kellys. Installed transmitter and reciever from cad 1.	CAD		\$921.40
003	6/24/2022 11:34	1444	7109 Hours	40253 Miles	While working on tag axle, and growling noise was identified and mass air leak started. Found fan hub at 400 degrees. Removed fan hub and disassembled. Found shaft scored badly.	REPAIR FAN HUB		\$1,080.00
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	Performed PM and Service. Changed engine oil and filter, and fuel filters. Air filter needs changed but no AF 1968 were in stock. Greased, adjusted brakes, adjusted clutch linkage. Found idler pulley bearing worn, removed and replaced with used idler off of c13 on stand. 39656 mi. 7059 hours.	PM INSPECTION		\$90.00
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	Remove old tank isolators, and install new ones with 3M sticky spray. Torqued straps to 35ft lbs	Safety Devices		\$30.00
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	Remove and replace AC expansion valve, compressor, and receiver drier. Installed new expansion valve, new receiver drier, and new compressor with new clutch. Recharged system	Reseal, service ac system, and replace compressor		\$439.85
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	Swapped out tag axle regulator with the regulator off of CAD 1	Swap out tag axle regulator		\$15.00
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	7059 hours. 39656 miles.	Service		\$178.21
003	6/21/2022 7:42	1433	7100 Hours	40161 Miles	Removed heater shut off valve and installed two new 1/4 turn ball valves on each end of hoses from heater core.	Install new heater shut off valves		\$30.00
003	6/16/2022 15:57	1441	7075 Hours	39818 Miles	Replaced ps down bag. Plumbed in new supply to switch	Repair tag axle		\$322.45
003	5/26/2022 17:28	1410	6962 Hours	38191 Miles	Replaced valve. Tightened front diff bolts.	Replaced ps height control valve		\$137.45
003	5/24/2022 7:31	1363	6932 Hours	37634 Miles	RePlace drag brake	CAD		\$0.00
003	5/3/2022 11:44	1371	6810 Hours	35467 Miles		Cab		\$58.06
003	5/3/2022 11:44	1371	6810 Hours	35467 Miles	Repair skirting. REMOVED OLD SKIRTING AND CUT NEW AND REPLACED SKIRTING AT HOPPER.	CAD		\$150.00
003	5/3/2022 11:44	1371	6810 Hours	35467 Miles	Greased chassis, checked boxes. Replaced oil, and fuel filters, filled oil. Also performed pm inspection.	Service		\$168.21
003	5/3/2022 11:44	1371	6810 Hours	35467 Miles	TESTED LIFT AXLE FOR NO DOWN PRESSURE, REMOVED REGULATOR AND GAUGE AT BACK OF CAB AND TESTED AIR LINES. NO PRESSURE AT REGULATOR, FOUND DASH TOGGLE SWITCH NOT WORKING, REMOVED AND INSTALLED NEW SWITCH, LIFT AXLE OPERATES EVERY TIME, STILL NO DOWN PRESSURE, ADJUSTED REGULATOR AND GOT AXLE DOWN PRESSURE TO 80 PSI BUT OPERATES SLOW, NEED TO REPLACE REGULATOR AT SOME POINT BUT OPERATES PROPERLY AT THIS TIME.	Suspension		\$215.00
003	5/3/2022 11:44	1371	6810 Hours	35467 Miles	Paint bumper. CLEANED AND PAINTED FRONT BUMPER	Safety Devices		\$30.00

003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	ADJUST SWING CHAINS. ADJUSTED PIVOT CHAIN.	CAD		\$45.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	REPLACE POTENTIOMETER. Disassembled control box and replaced speed potentiometer. Assembled box.	CAD		\$70.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	T/S AND REPAIR OIL TEMP SENSOR INOP. TESTED WIRING. TESTED GOOD. REMOVED AND REPLACED SENSOR	Engine		\$45.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	PERFORM ANNUAL INSPECTION, AND REPAIR ALL DISCREPENCIES	Inspection		\$60.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	REMOVED FRONT BUMPER AND STRAIGHTENED AND WELDED CRACKS IN BUMPER, SANDED BUMPER AND PAINTED BUMPER AND INSTALLED.	REPAIR FRONT BUMPER		\$175.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	DISCONNECTED BATTERIES AND REMOVED OLD 3 IN 1 ADAPTER AND WIRED IN NEW ONE. CHECKED BATTERIES AND CONNECTED.	Replace 3-1		\$45.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	T/S HYD. LEAKS AND FOUND HYD FILTER AND BASE LOOSE, TIGHTENED FILTER BASE AND REPLACED HYD. FILTER. REMOVED AND REPLACED VARIOUS HYD HOSES DUE TO RUBBED THROUGH AND LEAKING,	Hydraulics		\$345.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	T/S AND REPAIR TAG AXLE. T/s AND REPLACED DOWN BAG VALVE. TEST AFTER REPAIR. TAG AXLE OPERATES GOOD.	Suspension		\$90.00
003	4/4/2022 14:12	1322	6369 Hours	28773 Miles	CHANGE OIL, AND FILTER ON ENGINE. CHANGED FUEL FILTERS. REPLACE OIL IN TRANS, AND DIFFS. REPLACE HYDRAULIC FILTERS. GREASED CHASSIS.	Service		\$155.67
003	11/12/2021 11:34	1293	6242 Hours	26853 Miles	PERFORMED 250HR SERVICE, CHANGED ENGINE OIL AND FILTERS, GREASED CHASSIS. INSPECTED TRUCK AND CHECKED ALL BOXES. REPLACED P.S. FRONT DRIVE AXLE SHOCK.	2502HR SERVICE		\$414.98
003	11/12/2021 11:34	1293	6242 Hours	26853 Miles	PLUGGED INTO TRUCK AND CHECKED CODES FOR ABS SYSTEM, FOR CODE FOR DRIVER SIDE STEER WHEEL SENSOR OPEN. FOUND THAT THE WHEEL SENSOR WAS MISSING, INSTALLED NEW SENSOR, DROVE TRUCK TO SHUT OFF LIGHT. CLEARED CODES.	REPAIR ABS LIGHT		\$94.50
003	10/13/2021 13:18	1278	16108 Hours	24821 Miles	REPLACED CHAIN AND SPROCKET ON FEED BELT DRIVE.	REPAIR FEED BELT		\$90.00
003	10/13/2021 13:18	1278	16108 Hours	24821 Miles	REMOVED POWER STEERING PUMP AND RESEALED HYD. FITTING, INSTALLED PUMP AND CHECKED FOR LEAKS. NO LEAKS FOUND	REPAIR HYDRAULIC LEAK		\$31.25
003	10/4/2021 14:48	1275	14987 Hours	23825 Miles	PERFORMED ANNUAL INSPECTION, FOUND BRAKES NEED TO BE ADJUSTED.	PERFORM ANNUAL INSPECTION		\$35.00
003	10/4/2021 14:48	1275	14987 Hours	23825 Miles	CYL #1 HAS MISS, TESTED AND FOUND ENGINE HARNESS LEAKING OIL FROM TOP END AND THROUGH WIRING TO ECM, CAUSING ENGINE OIL TO EFFECT ECM. REMOVED AIR CLEANER AND AIR TUBES, REMOVED VALVE COVERS AND JAKE HOUSINGS. REMOVED JAKES, REMOVED ROCKER HOUSING AND REMOVED INJECTOR WIRE HARNESS, REMOVED ENGINE HARNESS, INSTALLED NEW HARNESSES, INSTALLED HOUSINGS AND AIR TUBES AND AIR CLEANER, TEST AFTER REPAIR AND NO ENGINE MISS.	T/S AND REPAIR ENGINE MISS		\$776.90
003	10/4/2021 14:48	1275	14987 Hours	23825 Miles	CHECKED KINGPINS AND ADJUSTED BRAKES,	CHECK KINGPINS AND BRAKES		\$56.25
003	10/4/2021 14:34	1268	14987 Hours	23825 Miles	RECOVERED A/C SYSTEM, REMOVED AND REPLACED A/C COMPRESSOR, DRYER, AND EXPANSION VALVE, REPLACED HIGH PSI SWITCH. CHARGED SYSTEM WITH 3.25 LBS OF R134A, REMOVED AIR TUBE AND BLOWER MOTOR DOOR, CHANGED OVER FAN SQUIRLE CAGES AND INSTALLED BLOWER FAN, TESTED AND FAN OPERATES, REPLACED FAN RESISTOR INSIDE DASH. A/C SYSTEM COOLS.	A/C SYSTEM NOT COOLING		\$922.96
003	9/22/2021 12:23	1266	14987 Hours	22918 Miles	REPLACED DOWN BAG ON LIFT AXLE AND REPLACED SLACK ADJUSTER ON P.S. STEER AXLE	REPLACE AIR BAG ON LIFT AXLE		\$112.50
003	9/22/2021 12:23	1266	14987 Hours	22918 Miles	PERFORMED 250HR SERVICE PER CHECKLIST	250HR SERVICE		\$261.06
003	9/14/2021 12:43	1262	14987 Hours	22410 Miles	CLUTCH ADJUST WITHIN SPEC, WAS ADJUSTED A WEEK EARLIER	CLUTCH ADJUSTMENT		\$17.50
003	9/14/2021 12:43	1262	14987 Hours	22410 Miles	JAKE BRAKE NOT WORKING DUE TO CRUISE SWITCH WAS ON, NEEDS TO BE OFF FOR JAKES TO OPERATE.	JAKES NOT WORKING		\$17.50
003	9/14/2021 12:43	1262	14987 Hours	22410 Miles	CHECKED EXHAUST PORT ON VALVE FOR LIFT AXLE AND WAS CLOGGED, CLEANED OUT AND AXLE OPERATES.	LIFT AXLE NOT OPERATING		\$37.50
003	9/2/2021 11:28	1251	14987 Hours	21527 Miles	T/S LIFT AXLE, TRACED AIR LINES AND FINALLY FOUND CONTROL VALVE WAS PLUMBED WRONG, MOVED AIR LINES TO CORRECT PORTS AND LIFT AXLE OPERATES PROPERLY, ALSO FOUND RIDE HEIGHT WAS UNEVEN, PASSENGER SIDE HEIGHT CONTROL VALVE LEAKING, REMOVED AND REPLACED VALVE, SET RIDE HEIGHT.	T/S AND REPAIR LIFT AXLE		\$311.20
003	8/24/2021 12:09	1236	14987 Hours	20150 Miles	FRONT RIGHT DRIVE AXLE BROKEN, REMOVED BROKEN AXLE AND REMOVED DIFF, CLEANED DIFF AND HOUSING, INSTALLED DIFF AND NEW AXLE. FILLED WITH OIL.	REPAIR BROKEN AXLE		\$439.99

003	8/24/2021 12:09	1236	14987 Hours	20150 Miles	REAR PIVOT BEARING FAILED, REMOVED COVERS AND REMOVED CHAINS, REMOVED SPROCKETS AND CUT OLD SHAFT IN HALF, CLEANED PARTS AND AREA, INSTALLED NEW SHAFT AND BEARINGS, INSTALLED SPROCKET AND CHAINS. INSTALLED COVERS AND TEST AFTER REPAIR, PIVOT SYSTEM OPERATES PROPERLY.	REPAIR REAR PIVOT BEARING		\$302.00
003	8/24/2021 12:09	1236	14987 Hours	20150 Miles	PLUGGED INTO ECM AND TRUCK HAD CODE FOR LOW OIL PRESSURE. CHECKED OIL PRESSURE AND FOUND PRESSURE GOOD BUT OIL PRESS. SENSOR FAILED. ORDERED NEW SENSOR AND INSTALLED, CLEARED CODES AND RAN TRUCK. NO OIL PRESS. CODE CAME BACK.	Engine		\$235.20
003	8/24/2021 12:09	1236	14987 Hours	20150 Miles	REMOVED SUPERSHEILD AND DISASSEMBLED. REMOVED DRIVE PULLEY SHAFT AND DISASSEMBLED. FOUND GOOD USED SHAFT UPSTAIRES, DISASSEMBLED AND INSTALLED PULLEYS ON GOOD SHAFT. INSTALLED NEW BEARINGS AND INSTALLED INTO SUPERSHEILD, INSTALLED SUPERSHEILD AND TESTED TRACKING, TESTED GOOD.	REPAIR SUPERSHEILD DRIVE		\$135.00
003	7/5/2021 10:35	1197	14987 Hours	0 Miles	FOUND AIR LINE GOING TO FINAL DRIVE LEAKING, CUT OUT BAD SPOT ON LINE AND SPLICED TOGETHER.	T/S AND REPAIR AIR LEAK		\$36.00
003	6/30/2021 10:33	1209	14987 Hours	0 Miles	RAN TRUCK AND FOUND OIL LEAKING REAL BAD AT BACK OF ENGINE.ALSO FOUND AIR COMPRESSOR PUSHING OIL OUT OF DISCHARGE PORT QUITE ALOT AND FILLING THE OIL SYSTEM WITH COOLANT, REMOVED AND REPLACED AIR COMPRESSOR. FOUND OIL PAN AND BLOCK RUBBER DIP STICK PLUGS LEAKING OIL EXTERNALLY EXCESSIVELY. DRAINED ENGINE OIL AND REMOVED OIL PAN, REMOVED DIP STICK BLOCK PLUGS AND CLEANED PAN AND BOTTOM OF BLOCK. INSTALLED NEW BLOCK PLUGS AND NEW OIL PAN GASKET, INSTALLED OIL PAN, FILLED WITH OIL AND REPLACED FILTER. RAN TRUCK AND CHECKED FOR LEAKS. NO LEAKS FOUND. ALSO REPAIRED A/C SYSTEM WITH NEW PRESSURE SWITCH, CHARGED SYSTEM AND SYSTEM COOLS.	T/S AND REPAIR ENGINE OIL LEAK		\$327.68
003	6/18/2021 14:30	1219	14987 Hours	39288 Miles	CHECKED OVER TRUCK AND CAD SYSTEM AFTER BOX FRAME REPAIR, CHECKED ALL FLUIDS AND CHASSIS. FOUND DRIVE CHAINS AND SLINGER CHAINS VERY DRY, CLEANED AND LUBBED ALL CHAINS.	CHECK OVER TRUCK AND CAD SYSTEM		\$28.00
003	6/18/2021 14:30	1219	14987 Hours	39288 Miles	TESTED AIR COMPRESSOR AND FOUND UNLOADER VALVES STICKING AND ALLOWING COMPRESSOR TO BYPASS. REMOVED COVER AND UNLOADER VALVES, CLEANED PARTS AND INSTALLED NEW UNLOADER VALVE KIT, INSTALLED COVER AND TEST AFTER REPAIR, AIR COMPRESSOR FUNCTIONS PROPERLY.	TRUCK AIR SYSTEM SLOW TO BUILD		\$56.00
003	6/18/2021 14:30	1219	14987 Hours	39288 Miles	PERFORMED 250HR SERVICE PER CHECKLIST. REPLACED OASSENGER SIDE FRONT OIL HUB CAP	250 HR service and repairs		\$190.92
003	6/18/2021 14:30	1219	14987 Hours	39288 Miles	CAD BOX FRAME RUSTED OUT AND NEED TO REPLACE BOTTOM BOX FRAME ON BOTH SIDES. DISCONNECTED HYD. LINES, CUT OFF ALL WELDS TO ACCESS FRAME TUBES. GRINDED AND CLEANED FRAME AREA, INSTALLED NEW FRAME TUBES AND WELDED IN, SET BOX DOWN ON TRUCK FRAME AND WELDED ON ACCY. AND INSTALLED HYD. LINES AND MISC.	REPAIR BOX FRAME RUSTED OUT		\$538.00
003	3/12/2021 12:02	1232	14987 Hours	0 Miles	DISCONNECTED AND REMOVED DRIVELINE AND TRANSMISSION. DISASSEMBLED AND REBUILT TRANSMISSION. INSTALLED NEW CLUTCH AND INSTALLED TRANSMISSION. INSTALLED DRIVELINE AND TEST AFTER REPAIR. TRANSMISSION SHIFTS AND OPERATES PROPERLY.	REBUILD TRANSMISSION		\$1,996.95
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles	Install battery maintainer	Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$50.18

003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Drivetrain	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$0.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Hydraulics	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$25.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Engine	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$250.49
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$20.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Engine	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$234.84
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$20.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$48.00

003	3/5/2021 19:01	1157	14987 Hours	39288 Miles	Adjust brakes	Brakes	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$16.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles	Replace clutch, and isolator. Also found that selector gear is worn, along with other gears.	Drivetrain	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$747.62
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		CAD	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$96.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Drivetrain	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$100.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles	Sample, drained and change fluids in trans and differentials	Drivetrain	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$154.74
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Cab	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$60.00
003	3/5/2021 19:01	1157	14987 Hours	39288 Miles	Install resistors to turn signals	Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$0.00

003	3/5/2021 19:01	1157	14987 Hours	39288 Miles		Electrical	Jake Removed all a/c lines, and austin ordered parts. Jake also drained transmission, removed hydraulic pumps, and PTO's and drivelines. Disconnected transmission, and removed transmission, clutch and flywheel. Rear main seal was found to be seeping and was ordered. Transmission top plate was removed and found that the sliding gear between 3rd and direct is extremely wore and gears need replaced. Dalton Removed front differential, and cleaned housing and helped install with austin. Dalton repaired tarp and resealed fittings on D/S gear box.	\$0.00
003	1/5/2021 10:28	1129	14987 Hours	39288 Miles		Cab	Replaced halogen lights with led, worked on reassembling truck.; Replaced right rear tag axle brake can.; REASSEMBLED SLINGER, REPLACED ALL SLINGER BEARINGS, REINSTALLED BELT, AND REINSTALLED HOPPER.; Finished reassembling truck. Rewired driver side headlight.	\$1,606.07
003	1/5/2021 10:28	1129	14987 Hours	39288 Miles		Electrical	Replaced halogen lights with led, worked on reassembling truck.; Replaced right rear tag axle brake can.; REASSEMBLED SLINGER, REPLACED ALL SLINGER BEARINGS, REINSTALLED BELT, AND REINSTALLED HOPPER.; Finished reassembling truck. Rewired driver side headlight.	\$56.00
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles		125 HR PM Inspection	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$48.00
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles		250 HR service and repairs	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$210.94
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles		Brakes	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$117.02
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles	Repair coolant leak on water pump.	Engine	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$12.00
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles		Drivetrain	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$0.00
003	12/14/2020 10:29	1127	14987 Hours	39288 Miles		CAD	Performed inspection. Drained oil, changed oil, and fuel filters. Greased chassis, checked boxes, brakes, and all fluids. Replaced wheel seal and brakes on P/S steer axle.; Oil change performed at 4987 HR; Removed hydraulic lines from gate 4 valve. Removed electrical plug, removed actuator. Cleaned valve, installed new actuator, reinstalled plug, and reinstalled hydraulic lines. Tested actuator, and found gate 4 works now,	\$28.00
003	12/2/2020 19:58	1124	14771 Hours	39288 Miles		hydraulics	Replaced blown hose on pivot cylinder.	\$75.80

003	10/7/2020 19:00	1067	4738 Hours	39288 Miles	Driver side tag axle brake can broke	Brakes	Found u joint bad. Removed driveline. Removed u joint, drove to tnt to pick up parts. Installed new u joint, reinstalled and torqued driveline.; Changed oil, oil filter, fuel filter, and checked air filter. Checked fluid in boxes, installed oil filter 1792, fuel filters 3528,3674. Oil changed at 4738 next due at 4988. During oil change found driver side tag axle brake can broke.; Removed old brake can from driver side tag axle. Cut to length and installed new can.	\$48.00
003	10/7/2020 19:00	1067	4738 Hours	39288 Miles		125 HR PM Inspection	Found u joint bad. Removed driveline. Removed u joint, drove to tnt to pick up parts. Installed new u joint, reinstalled and torqued driveline.; Changed oil, oil filter, fuel filter, and checked air filter. Checked fluid in boxes, installed oil filter 1792, fuel filters 3528,3674. Oil changed at 4738 next due at 4988. During oil change found driver side tag axle brake can broke.; Removed old brake can from driver side tag axle. Cut to length and installed new can.	\$0.00
003	10/7/2020 19:00	1067	4738 Hours	39288 Miles		250 HR service and repairs	Found u joint bad. Removed driveline. Removed u joint, drove to tnt to pick up parts. Installed new u joint, reinstalled and torqued driveline.; Changed oil, oil filter, fuel filter, and checked air filter. Checked fluid in boxes, installed oil filter 1792, fuel filters 3528,3674. Oil changed at 4738 next due at 4988. During oil change found driver side tag axle brake can broke.; Removed old brake can from driver side tag axle. Cut to length and installed new can.	\$72.00
003	10/7/2020 19:00	1067	4738 Hours	39288 Miles		Drivetrain	Found u joint bad. Removed driveline. Removed u joint, drove to tnt to pick up parts. Installed new u joint, reinstalled and torqued driveline.; Changed oil, oil filter, fuel filter, and checked air filter. Checked fluid in boxes, installed oil filter 1792, fuel filters 3528,3674. Oil changed at 4738 next due at 4988. During oil change found driver side tag axle brake can broke.; Removed old brake can from driver side tag axle. Cut to length and installed new can.	\$152.95
003	9/23/2020 10:19	1042	0 Hours	0 Miles		Inspection	Inspected truck. Repaired PS lower tail light. Repaired DS rear side tail light. Tightened Steering chain, Hydraulic steering valve box leaking. 2 missing reflectors. back of transmission wet.	\$87.50