

Unit #	Completed	WO	HOURS	MILES	Task Note	Task	Notes	Total Cost
001	11/6/2023 13:42	1896	4388 Hours	500747 Miles		Engine - Fluids/Belts/Other		\$15.00
001	11/6/2023 13:42	1896	4388 Hours	500747 Miles		CAD/Transfer/Dump Function		\$22.50
001	11/6/2023 11:16	1862	4344 Hours	500132 Miles	Replace slinger belt	CAD		\$780.00
001	11/6/2023 11:16	1862	4344 Hours	500132 Miles	Put on a new fan switch knob. Mileage 500132 hours 4344	Check blower motor at all speeds		\$1.60
001	11/6/2023 11:16	1862	4344 Hours	500132 Miles	Pulled out the old washer motor, and put on a new one.	Check Washer Fluid		\$43.67
001	11/6/2023 11:08	1884	4388 Hours	500747 Miles	Replaced slinger belt with new one, replaced both hyd. Hoses off of slinger motor and converted to chain system from belt. Found belt to be too short from specified size and removed entire slinger and installed spare manual slinger.	Slinger belt had tear in it.		\$128.00
001	10/9/2023 11:26	1870	4244 Hours	498687 Miles	REPLACED HYDRAULIC FAN SWITCH.	Electrical		\$10.00
001	9/26/2023 16:08	1850	4201 Hours	498212 Miles		Lube Service		\$326.85
001	9/13/2023 8:13	1838	3868 Hours	493908 Miles		Lube Service	Driver screwed up hour disregard work order	\$0.00
001	8/17/2023 14:48	1797	4062 Hours	496415 Miles		Brakes		\$102.52
001	8/17/2023 14:48	1797	4062 Hours	496415 Miles	#2 fuel line from fuel injection pump broke. Need to replace all lines except #5. Also need to replace #3 injection pump.	Engine		\$1,783.21
001	8/17/2023 14:48	1797	4062 Hours	496415 Miles	Reseal danfrost multi valve	Hydraulics		\$240.00
001	8/17/2023 14:48	1797	4062 Hours	496415 Miles	Inspect front spring pins.	Suspension		\$0.00
001	7/24/2023 12:08	1765	4007 Hours	495735 Miles	Rewelded broken trough roller. and help seal up discharge system.	CAD		\$30.00
001	6/16/2023 12:16	1754	3868 Hours	493908 Miles		Annual Inspection		\$40.00
001	6/16/2023 12:16	1754	3868 Hours	493908 Miles	Changed engine oil and filter, both fuel filters, greased, checked boxes, etc per inspection sheet. 493908 miles. 3868 hours	Lube Service		\$608.33
001	6/16/2023 12:16	1754	3868 Hours	493908 Miles	Found Bonnet seals leaking from fuel injection pump. Removed fuel lines. and removed bonnet caps. Replaced bonnet seals, and reassembled. Also found AFRC diaphragm bad, causing lack of power. Replaced with spare.	Engine - Fluids/Belts/Other		\$120.00
001	6/16/2023 12:16	1754	3868 Hours	493908 Miles	Replaced straps on rear u joint of stub shaft.	Drivetrain		\$23.49
001	5/8/2023 11:38	1709	3700 Hours	491464 Miles	Replaced steering helper cylinder. PN 10-02675	Steering		\$2,355.00
001	3/15/2023 15:27	1655	3643 Hours	490880 Miles	Replaced the driver side front dive slack adjuster	Safety Devices		\$74.95
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles		TABLET MOUNT		\$109.98
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles		SERVICE AIR DRYER		\$78.00
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles		REBUILD SUSPENSION		\$2,345.72
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles	Fiber glass and bondo repair to broken corner of hood	REPAIR HOOD		\$175.00
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles		ANNUAL INSPECTON		\$35.00
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles	Ran ground wire into master.	CHECK CAD SYSTEM		\$35.00
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles	Replaced drive axle brakes	Brakes		\$787.96
001	3/2/2023 8:24	1454	3619 Hours	490554 Miles		REPLACE DIFF, AND TRANS OIL		\$825.20
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		BRAKES		\$549.24
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		TABLET MOUNT		\$49.99
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		REPLACE TRANSMISSION FLUID		\$156.95
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles	Put on a new hydraulic cap.	Hydraulics		\$11.02
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		SERVICE AIR DRYER		\$78.00
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		Suspension		\$1,972.64
001	1/20/2023 9:43	1617	3653 Hours	490937 Miles		REPAIR HOOD FENDER		\$210.00
001	11/3/2022 9:59	1559	3543 Hours	489692 Miles	Replace the Flexco on the feed belt.	CAD		\$90.00
001	11/3/2022 9:59	1559	3543 Hours	489692 Miles		Air System		\$259.50
001	10/31/2022 12:26	1552	3543 Hours	489692 Miles	Replaced Input U joint on rear diff. Drained and changed both differential fluids. 3543 hours. 489,692 mi.	Drivetrain		\$96.75
001	10/31/2022 12:26	1552	3543 Hours	489692 Miles	Changed engine oil and filter, both fuel filters. 3543 hrs. 489,692 miles	Service		\$215.45
001	10/31/2022 12:26	1552	3543 Hours	489692 Miles	Performed PM and service. Changed engine oil and filter, both fuel filters, greased, checked boxes etc per inspection sheet. Through inspection found one cross member with crack, another with loose bolts, slight leak between rear diff and housing, and one u joint worn out. 3543 hours. 489,692 mi	Inspection		\$60.00
001	8/9/2022 9:27	1445	3082 Hours	483850 Miles	REMOVED HYDRAULIC PUMP, FOUND SPLINES ON SHAFT IN GOOD CONDITION. FOUND PUMP HAD FAILED INTERNALLY, ORDERED NEW PUMP. INSTALLED NEW PUMP, BUT HAD TO ROB CAD TRANSMITTER AND RECIEVER OFF OF TRUCK TO GET CAD 3 GOING. INSTALLED TRANSMITTER AND RECIEVER FROM CAD 3 ONTO CAD 1.	T/S HYDRAULIC SYSTEM		\$2,160.12

001	6/24/2022 11:33	1366	3082 Hours	483850 Miles	PERFORMED ANNUAL INSPECTION AND FOUND TAG AXLE BUSHINGS WORN AND LOOSE, TORQUE ARM OVER REAR DRIVE AXLE LOOSE, 2 CROSS MEMBERS BOLTS LOOSE.	Annual inspection		\$30.00
001	6/24/2022 11:33	1366	3082 Hours	483850 Miles	Drained coolant, removed coolant lines and air gov. Removed air compressor. Swapped over fittings, installed new compressor and made new coolant hose, found power steering reservoir bracket broken. Removed broken bracket and installed new bracket and tighten. Topped off power steering fluid. Filled with coolant.	Engine		\$192.82
001	6/24/2022 11:33	1366	3082 Hours	483850 Miles	Remove tag axle. Clean up frame for new tag axle. Installed new tag axle. Removed all old air lines and unused air lines. Ran new air lines, made sure tag operates, made sure it goes up in reverse.	Drivetrain		\$1,080.00
001	6/21/2022 7:42	1424	3082 Hours	483850 Miles	Install new cross member	Cab		\$15.00
001	6/21/2022 7:42	1424	3082 Hours	483850 Miles		Service		\$63.52
001	6/21/2022 7:42	1424	3082 Hours	483850 Miles	Performed PM and service. Topped off differential fluids. Changed engine oil and filter, fuel filters. Greased, adjusted brakes. Noticed rear drive axle u joints had some play. Frame cross member over front differential is crack and needs replaced.	Inspection		\$45.00
001	6/21/2022 7:42	1424	3082 Hours	483850 Miles	Replace pivot shaft and bearings, replace both pivot and swing chain. Removed pivot motor gearbox, reinstalled without. Waiting on new gearbox to arrive	CAD		\$607.22
001	6/21/2022 7:42	1424	3082 Hours	483850 Miles		Air System		\$40.25
001	6/13/2022 15:41	1435	3082 Hours	483850 Miles	Change main hydraulic filter. Mileage 0484880 hours 3191	Hydraulics		\$7.50
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles		Electrical	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$0.00
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles		Cab	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$1,325.75
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles		Electrical	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$83.99
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles		CAD	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$250.00
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles	Replace tag axle shocks.	Suspension	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$157.00
001	2/8/2022 17:30	1130	1953 Hours	467550 Miles	REBUILD SLINGER, AND INSTALL NEW HOPPER. REBUILD SUPER SHIELD.	CAD	Reassembled after painting, made all repairs during assembly. Rebuilt slinger with new hopper, had to retrofit supershield to correspond with new hopper. Welded on and modified new hopper mounts. Changed all lights to led. Replaced tag axle shocks.	\$816.06
001	10/25/2021 14:16	1287	2886 Hours	481170 Miles	PERFORMED 250HR SERVICE PER CHECKLIST, CHANGED OIL AND FILTER AND FUEL FILTERS, GREASED AND INSPECTED CHASSIS.	250HR SERVICE		\$262.51
001	10/8/2021 12:14	1276	25790 Hours	479645 Miles	REMOVED AND INSTALLED NEW SUSPENSION AIR BAG	REPLACE BLOWN AIR BAG		\$145.75
001	9/27/2021 10:47	1269	25790 Hours	477980 Miles	REAR SUSPENSION U-BOLT MOUNT AND WEAR PADS BROKEN, LIFTED AND SUPPORTED TRUCK AND REMOVED TIRES AND REMOVED REAR SUSPENSION. DISASSEMBLED AND REPLACED WEAR PADS AND U-BOLT MOUNTS AND U-BOLTS, REPLACED 2 AIR BAGS, REPLACED WHEEL SEAL ON PASSENGER SIDE STEER AXLE AND INSTALLED TIRES AND LOWERED TRUCK OFF OF JACKS.	REPAIR SUSPENSION		\$2,179.74

001	9/27/2021 10:47	1269	25790 Hours	477980 Miles	REMOVED OLD AIR HORNS AND MODIFIED NEW HORNS TO MOUNT. PLUMMED IN HORNS AND TESTED. ALSO REPLACED LEAKING HYDRAULIC HOSE ON GATE CYLINDER.	Cab		\$123.98
001	9/27/2021 10:47	1269	25790 Hours	477980 Miles	PERFORMED ANNUAL INSPECTION AFTER REPAIRS ON SUSPENSION AND CAB DISCREPENCIES.	PERFORM ANNUAL INSPECTION		\$35.00
001	9/24/2021 14:29	1179	25790 Hours	477980 Miles		Cab		\$32.00
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	REMOVED AND INSTALLED NEW PASSENGER SIDE WIPER ARM	REPLACE WIPER ARM		\$102.45
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	FOUND THAT THE JONNY BAR WAS APPLIED A LITTLE BIT CAUSING THE BRAKE LIGHTS TO STAY ON, WENT THROUGH AND ADJUSTED ALL BRAKES.	T/S BRAKES		\$25.00
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	REMOVED AND INSTALLED NEW BRAKE SLACK ADJUSTER ON PASSENGER STEER.	Brakes		\$104.95
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	PERFORMED PM SERVICE PER CHECKLIST	250 HR SERVICE		\$222.55
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	REMOVED DRIVER SIDE HUB CAP, CLEANED AND RESEALED WITH NEW GASKET. FILLED HUB	REPAIR STEER AXLE HUB CAP		\$25.00
001	9/8/2021 10:38	1252	25790 Hours	477470 Miles	AIRED UP TRUCK AIR SYSTEM AND CHECKED TRUCK FOR NOTICEABLE AIR LEAKS, NO LEAKS DETECTED.	CHECK FOR AIR LEAKS		\$25.00
001	7/29/2021 13:08	1201	2325 Hours	472615 Miles	DURRING INSPECTION FOUND METAL CHUNKS IN FRONT DIFF PLUG. REMOVED DRIVE LINE, REMOVED AIR TUBES AND DISCONNECTED AND DRAINED FRONT DIFF. REMOVED DIFF AND FOUND SIDE GEARS AND BEARINGS COMING APART. CLEANED HOUSING AND INSTALLED NEW DIFF. CONNECTED DIFF AND INSTALLED AIR TUBES AND DRIVELINE. FILLED WITH OIL.	R&R FRONT DIFFERENTIAL		\$1,692.70
001	7/29/2021 13:08	1201	2325 Hours	472615 Miles	REMOVED AIR TUBES, REMOVED VALVE COVERS AND JAKE HOUSINGS. RECOVERED A/C SYSTEM, REMOVED HOSES OUT OF WAY TO ACCESS VALVE COVERS. CHECKED AND ADJUSTED INLET AND EXHAUST VALVES, ADJUSTED JAKES. INSTALLED VALVE COVERS AND JAKE HOUSINGS, INSTALLED A/C HOSES, CHARGED A/C SYSTEM.	PERFORM VALVE ADJUST		\$112.00
001	7/29/2021 13:08	1201	2325 Hours	472615 Miles	PERFORMED 125 HR INSPECTION PER CHECKLIST. FOUND AND REPAIRED AIR LEAK. ALSO FOUND METAL IN FRONT DIFFERENTIAL.	125 HR INSPECTION		\$72.00
001	7/26/2021 11:35	1192	2325 Hours	472615 Miles	REPAIRED MARKER LIGHTS AND WIRING	Electrical		\$12.00
001	7/26/2021 11:35	1192	2325 Hours	472615 Miles	REPLACE RIGHT STEER WHEEL SEAL. REMOVED RH STEER WHEEL AND DISASSEMBLED HUB, INSPECTED WHEEL BEARINGS. BEARINGS CHECKED GOOD. INSTALLED BEARINGS AND NEW WHEEL SEAL. INSTALLED HUB AND REPLACED BRAKE SHOES. ASSEMBLED WHEEL ASSY AND ADJUSTED BRAKE.	Tires and Wheels		\$177.81
001	7/26/2021 11:35	1192	2325 Hours	472615 Miles	PERFORMED 250HR SERVICE, CHANGED OIL, FILTER AND FUEL FILTERS, GREASED CHASSIS.	Service		\$253.13
001	6/18/2021 14:35	1206	2325 Hours	472615 Miles	INSTALLED CAMERA. REMOVED DASH AND INSTALLED MODULE BEHIND DASH AND WIRED IN MODULE. INSTALLED DASH	INSTALL DASH CAMERA		\$28.00
001	5/17/2021 14:29	1225	2325 Hours	472615 Miles	CUT WIRING AND WIRED IN NEW PTO ELECTRICAL CONNECTOR. TESTED AND PTO ENGAGES AND LIGHT COMES ON	REPAIR WIRING TO PTO		\$35.55
001	5/17/2021 14:29	1225	2325 Hours	472615 Miles	INSTALLED CHAIN ON STEERING SHAFT	T/S AND REPAIR POWER STEERING		\$84.00
001	12/4/2020 15:25	1112	1897 Hours	466871 Miles		125 HR PM Inspection	Performed inspection and oil change. Found that brake lining on rear drive axle is wearing uneven. Found aluminum center crossmember is cracked. Oil leak on air compressor, and oil pan. Output seal on front differential leaking. Also found that radiator cap needs replaced. Drained oil, greased and inspected chassis, and checked boxes. Blew dirt out of air filter, replaced fuel and oil filters, and filled with oil	\$70.00
001	12/4/2020 15:25	1112	1897 Hours	466871 Miles		250 HR service and repairs	Performed inspection and oil change. Found that brake lining on rear drive axle is wearing uneven. Found aluminum center crossmember is cracked. Oil leak on air compressor, and oil pan. Output seal on front differential leaking. Also found that radiator cap needs replaced. Drained oil, greased and inspected chassis, and checked boxes. Blew dirt out of air filter, replaced fuel and oil filters, and filled with oil	\$60.00
001	12/4/2020 15:02	1118	1953 Hours	467550 Miles		Engine	Found jake switch out of adjustment, and loose. Replaced lock nut, and readjusted jake switch.	\$28.00
001	10/5/2020 9:21	1057	1575 Hours	462038 Miles		Electrical	Tested and changed 2 batteries.	\$274.70

001	9/28/2020 9:00	1051	1575 Hours	462038 Miles	Replace steering shaft.	Steering	Performed annual inspection. Discrepancies found were, missing marker light, loose cross member bolts, and exhaust leaks. Also found tag axle brake cans rusted through. Steering shaft excessively loose, new shaft ordered.; Repaired marker light during inspection, and adjusted brakes.; Replaced both tag axle brake cans.; Replaced back up alarm; Replaced steering shaft, and swapped over steering sprocket for remote steering.; Replaced muffler, and adjusted brakes.	\$572.86
001	9/28/2020 9:00	1051	1575 Hours	462038 Miles	Repair exhaust leak under cab, and replace muffler.	Exhaust	Performed annual inspection. Discrepancies found were, missing marker light, loose cross member bolts, and exhaust leaks. Also found tag axle brake cans rusted through. Steering shaft excessively loose, new shaft ordered.; Repaired marker light during inspection, and adjusted brakes.; Replaced both tag axle brake cans.; Replaced back up alarm; Replaced steering shaft, and swapped over steering sprocket for remote steering.; Replaced muffler, and adjusted brakes.	\$272.25
001	9/28/2020 9:00	1051	1575 Hours	462038 Miles		Inspection	Performed annual inspection. Discrepancies found were, missing marker light, loose cross member bolts, and exhaust leaks. Also found tag axle brake cans rusted through. Steering shaft excessively loose, new shaft ordered.; Repaired marker light during inspection, and adjusted brakes.; Replaced both tag axle brake cans.; Replaced back up alarm; Replaced steering shaft, and swapped over steering sprocket for remote steering.; Replaced muffler, and adjusted brakes.	\$138.95
001	9/28/2020 9:00	1051	1575 Hours	462038 Miles	Replace tag axle brake cans.	Brakes	Performed annual inspection. Discrepancies found were, missing marker light, loose cross member bolts, and exhaust leaks. Also found tag axle brake cans rusted through. Steering shaft excessively loose, new shaft ordered.; Repaired marker light during inspection, and adjusted brakes.; Replaced both tag axle brake cans.; Replaced back up alarm; Replaced steering shaft, and swapped over steering sprocket for remote steering.; Replaced muffler, and adjusted brakes.	\$246.00