

004	5/1/2023 8:39	1695	15965 Hours	232018 Miles	232018 miles. 15965 hours. Changed engine oil and filter, both fuel filters, power steering filter etc all per inspection sheet. Changed both differential fluid.	Lube Service		\$820.32
004	4/13/2023 13:58	1683	15830 Hours	230701 Miles	Replaced the block heater.	Engine		\$0.00
004	3/6/2023 8:32	1640	15759 Hours	229683 Miles		Hub Oils		\$54.45
004	3/1/2023 9:18	1627	15679 Hours	228740 Miles	Replace feed belt	CAD		\$650.00
004	2/7/2023 16:53	1619	15679 Hours	228740 Miles		Replaced Hydraulic Fan Switch		\$0.00
004	1/12/2023 8:54	1614	15679 Hours	228740 Miles	Pulled dust covers, inspected, and adjusted all drive and steer brakes. Replaced clevis pins on ps rear drive axle brakes.	Brakes		\$90.00
004	1/12/2023 8:54	1614	15679 Hours	228740 Miles	FOUND STEERING GEAR BOX HAD PLAY. ADJUSTED GEAR BOX.	Steering		\$35.00
004	1/12/2023 8:54	1614	15679 Hours	228740 Miles	Changed engine oil and filter, both fuel filters. Greased chassis, and performed pm inspection. 228, 740 miles. 15679 hrs.	Lube Service		\$200.72
004	12/6/2022 15:11	1573	15119 Hours	221789 Miles	Fixed the Flexco Splice on the feed belt. It didn't get installed right.	CAD		\$30.00
004	10/25/2022 15:18	1539	15119 Hours	221789 Miles	Replace the swing bearings, with a new swing shaft and chains.	CAD		\$482.14
004	10/25/2022 15:18	1539	15119 Hours	221789 Miles	Had to put a new idler pulley out in the field.	Engine		\$0.00
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	Put a strap kit on the u-joint behind the final drive.	Drivetrain		\$15.99
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	Jake replaced drivers side round mirror.	Safety Devices		\$17.50
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	Performed PM and Service. Changed engine oil and filter, fuel filters and air filter. Greased, adjusted brakes, checked boxes etc per inspection sheet. Through inspection found leaky wheel seal and oil soaked brake shoes in need of replacement, one U joint with caps spinning so new strap kit was installed. 15350	Inspection		\$60.00
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	HEAD PULLEY REPLACEMENT. Head pulley was ovaled and bearings were in need of replacement. Removed and replaced head pulley and bearings with new ones. 15,350 hrs.	CAD		\$307.08
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	Changed engine oil and filter, fuel filters and air filter. 15350 hrs. 224,881 mi.	Service		\$244.15
004	9/23/2022 9:04	1529	15119 Hours	221789 Miles	Through PM inspection found leaky wheel seal and brake shoes in need of replacement on drivers side steer axle. Pulled hub and also found bearing in need of replacement. Hub bearings and races, seal and brake shoes were all replaced. 15350 hrs.	Brakes		\$446.83
004	9/8/2022 9:25	1525	15119 Hours	221789 Miles	Changed 4 of 5 heim joints on clutch rods. Parts not yet in stock.	Clutch Rod Heim Joints		\$68.80
004	8/18/2022 13:36	1467	15119 Hours	221789 Miles	FOUND LIFT OPERATION INOP. TESTED SYSTEM, FOUND THAT ACTUATOR WAS INOP, CHANGED LIFT ACTUATOR.	CAD		\$65.00
004	8/18/2022 13:36	1467	15119 Hours	221789 Miles	SERVICE COMPLETED AT 220513 MILES, 15029 HOURS	Service		\$63.57
004	8/18/2022 13:36	1467	15119 Hours	221789 Miles		Inspection		\$45.00
004	8/18/2022 13:36	1467	15119 Hours	221789 Miles	FOUND BOTH DRIVERSIDE HYDRAULIC FANS INOP, REMOVED OLD FANS, INSTALLED NEW FANS AND REWIRED.	Hydraulics		\$52.50
004	8/9/2022 14:36	1499	15119 Hours	221789 Miles	Put on a new A/C tensioner pulley	Air System		\$7.50
004	7/20/2022 8:18	1479	15029 Hours	220513 Miles	Service. Changed engine oil and filter, fuel filters and cleaned air filter.	Service		\$178.47
004	7/20/2022 8:18	1479	15029 Hours	220513 Miles	Performed Pm and Service. Changed engine oil and filter, fuel filters, cleaned air filter, greased, adjusted brakes. Through inspection noticed front differential input yoke had some play. Marker light on rear of box also was out, put on good used light from shelf. 220, 513 miles. 15029 hrs.	Inspection		\$62.78
004	7/20/2022 8:18	1479	15029 Hours	220513 Miles	Austin fixed tarp system.	Safety Devices		\$105.00
004	6/22/2022 7:35	1448	14929 Hours	219419 Miles	Found turn signal switch bad. Had to disassemble steering column, and remove steering wheel. Installed new switch and	REPLACE TURN SIGNAL SWITCH		\$134.95
004	6/21/2022 7:49	1447	14918 Hours	219225 Miles	FOUND PS TAIL LIGHTS OUT ON BOX. CHECKED JUNCTION BOX, FOUND NO ISSUES. REMOVED MIDDLE LIGHT AND FOUND BAD CONNECTION. REPLACED CONNECTION, LIGHTS OPERATIONAL.	REPAIR TAIL LIGHTS		\$45.00
004	6/17/2022 10:36	1442	14865 Hours	218483 Miles		REPLACE BAD TAIL LIGHT		\$30.33

004	6/15/2022 13:22	1436	14865 Hours	218483 Miles		Electrical		\$230.00
004	6/15/2022 13:22	1436	14865 Hours	218483 Miles	Replace the tail pull and pillow blocks with new bearings.	CAD		\$210.38
004	6/15/2022 13:22	1436	14865 Hours	218483 Miles	Passenger side hydraulic cooler fan not working. Removed and replaced with used one from shelf. Had to make new custom brackets in order to mount. Replaced fan switch. Replace all hydraulic filter and indicators on the filters too.	Hydraulics		\$120.00
004	6/15/2022 13:22	1436	14865 Hours	218483 Miles	Removed air dryer. Replaced dryer cartridge and purge valve. Purge valve not yet in inventory. Reinstalled. 218,760 mi. 14887	Air System		\$142.75
004	6/13/2022 15:55	1434	14865 Hours	218483 Miles	Replace main hydraulic filters, and new hydraulic cap. Mileage 218626 hours 14876	Hydraulics		\$37.95
004	5/27/2022 13:16	1413	14759 Hours	217019 Miles	Replace compressor governor	Air System		\$72.70
004	5/27/2022 13:16	1413	14759 Hours	217019 Miles	Replaced feed potentiometer	CAD		\$8.75
004	5/25/2022 14:17	1397	14759 Hours	217019 Miles	CHANGED ENGINE OIL AND FILTER, CHANGED FUEL FILTERS	Service		\$223.21
004	5/25/2022 14:17	1397	14759 Hours	217019 Miles	PTO GOT STUCK ENGAGED DURING OPERATION, PULLED TRUCK IN AND DRAINED TRANSMISSION, REMOVED HYD. PUMP AND REMOVED PTO, DISASSEMBLED PTO AND REPLACED DRIVE GEAR, DOSASSEMBLED AND INSPECTED SHIFT FORK HOUSING, INSPECTED TRANSMISSION FOR DAMAGE AND NO DAMAGE FOUND, INSTALLED PTO AND CHECKED BACKLASH, CHECKED GOOD. INSTALLED SHIFT FORK. INSTALLED HYD PUMP AND	Drivetrain		\$332.50
004	5/24/2022 7:26	1393	14741 Hours	216813 Miles	The feed had tracked over and the Flexco had caught on the tail pulley and stop the bet. Cut a 1/4" off the Flexco rod and worked on getting the belt unstuck.	CAD		\$325.00
004	5/19/2022 16:33	1395	14734 Hours	216761 Miles	Service call. Found pto output seal pushed out. Removed hydraulic pump, put loctite on seal and pined around seal. Reinstalled hydraulic pump. And filled trans.	Drivetrain		\$130.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Replace back up alarm, and back up lights. FABRICATED FOG LIGHT BRACKETS AND PAINTED MOUNTS, INSTALLED LIGHTS AND WIRED IN. REPLACED BACK UP ALARM.	Safety Devices		\$153.95
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles		Inspection		\$114.15
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Repair skirting on back end of feed belt. REMOVED ALL RUBBER SKIRTING AND SHOOT, CUT NEW RUBBER AND STARTED INSTALLING NEW SHOOT AND SKIRTING AT BACK OF CAD	CAD		\$240.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Reroute water and hydraulic hoses on driver side of frame.	CAD		\$0.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	REMOVED AND INSTALLED NEW SLINGER PIVOT HYD. HOSES. REPLACED HOSES FOR CAD SYSTEM	Hydraulics		\$360.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	DISCONNECTED AND REMOVED EXPANSION VALVE, INSTALLED NEW VALVE, LOOSENED LOW PRESSURE A/C LINE AND REPOSITIONED, ADDED 2OZ. OF PAG OIL TO SYSTEM. PULLED VACCUM AND CHARGED SYSTEM WITH 3.10 LBS OF R134a. RAN LEAK SNIFFER OVER ENTIRE SYSTEM AND FOUND NO LEAKS. IF A/C SYSTEM LEAKS OUT LATER THEN NEED TO REPLACE THE BIG LINE AT THE EXPANSION VALVE TO COMPRESSOR.	AC		\$269.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Replace windshields	Cab		\$265.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	LOOSENED RADIATOR AND DISCONNECTED AND REMOVED FAN HUB. DISASSEMBLED FAN HUB AND FOUND BEARING CARRIER WAS CRACKED, NEED TO REPLACE COMPLETE FAN HUB ASSY. ORDERED NEW FAN HUB. INSTALLED NEW FAN HUB ON FRONT OF ENGINE AND CONNECTED. INSTALLED NEW HUB AIR LINE. TIGHTENED UP RADIATOR SUPPORTS AND CONNECTED	Air System		\$1,049.95
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles		Suspension		\$315.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Replace all suspension air bags. BODEN WORKED ON REPLACING ALL SUSPENSION AIR BAGS, REMOVED AND INSTALLED WITH NEW BAGS, TRAVIS HELPED.	Suspension		\$1,281.00

004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Replace driver seat	Cab		\$739.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Tail pulley shaft is worn. Replace tail pulley and check bearings. Also check bearings on swing shaft	CAD		\$0.00
004	5/3/2022 12:21	1343	14605 Hours	214575 Miles	Replace pintle hitch. REMOVED AND INSTALLED NEW PINTLE	Safety Devices		\$100.99
004	4/17/2022 19:34	1358	14100 Hours	207083 Miles	Replaced mirror	Cab		\$79.50
004	1/19/2022 12:23	1310	14100 Hours	207083 Miles		TIGHTEN AND SECURE AIR TANK		\$12.50
004	1/19/2022 12:23	1310	14100 Hours	207083 Miles	REPAIRED WIRING TO TAIL AND BRAKE LIGHTS, WIRED IN AND INSTALLED NEW FRONT MARKER AND TURN SIGNAL LIGHTS.	Electrical		\$95.00
004	1/19/2022 12:23	1310	14100 Hours	207083 Miles	PERFORMED 250 HR SERVICE PER CHECKLIST	250HR SERVICE		\$319.92
004	12/7/2021 15:10	1281	14033 Hours	206049 Miles	SWING SHAFT BEARINGS FAILED, UNBOLTED AND DISASSEMBLED SWING SHAFT, CLEANED PARTS, REPLACED BEARINGS AND SHAFT. ASSEMBLED AND TESTED.	REPAIR SWING SHAFT BEARINGS		\$183.75
004	12/7/2021 15:10	1281	14033 Hours	206049 Miles	UNBOLTED AND REMOVED SLINGER AND DRIVE AXLE HALF FENDERS, CUT OFF FENDER MOUNTS TO MOVE MOUNTS HIGHER TO ACCOMMODATE TIRE CHAINS. GROUND FRAME SMOOTH WHERE MOUNTS WERE WELDED. MADE NEW FENDER BRACKETS FOR DRIVE AXLES. INSTALLED BRACKETS AND INSTALLED FENDERS. INSTALLED SLINGER AND GREASED TRUCK.	MODIFY DRIVE AXLE FENDERS		\$1,592.50
004	12/7/2021 15:10	1281	14033 Hours	206049 Miles	CORRODED AND SHORTED WIRES IN REAR JUNCTION BOX, REMOVED AND REPLACED REAR JUNCTION BOX. STILL HAS WIRING ISSUE THAT NEEDS TO BE T/S.	REPAIR TAIL LIGHTS		\$180.95
004	12/7/2021 15:10	1281	14033 Hours	206049 Miles	HAD FIELD CALL TO T/S PTO EXCESSIVE NOISE AND LOCKED UP, FOUND PTO BROKE MAIN PTO SHAFT BEARINGS AND GEAR COCKED IN HOUSING AND DAMAGED TRANSMISSION PTO GEAR AND AUXILIARY SHAFT. PULLED TRUCK INTO SHOP AND REMOVED DRIVELINES AND CROSSMEMBER. REMOVED SHIFT TOWER AND AIR LINES, REMOVED TRANSMISSION, CLUTCH, AND FLYWHEEL. DISASSEMBLED AND WORKED ON REBUILDING DAMAGED PTO. ORDERED PTO PARTS. REBUILT PTO AUXILIARY DRIVE. FOUND REAR ENGINE HOUSING LEAKING, REMOVED OIL PAN AND SECURED ENGINE, REMOVED HOUSING AND CLEANED, RESEALED AND INSTALLED REAR HOUSING, INSTALLED FLYWHEEL AND CLUTCH. INSTALLED NEW CROSS SHAFTS AND FORK AND CLUTCH BRAKE. INSTALLED TRANSMISSION, CONNECTED TRANSMISSION AND INSTALLED DRIVELINE AND CROSSMEMBERS, INSTALLED AND CONNECTED PTOS. INSTALLED OIL PAN AND FILLED WITH ENGINE OIL AND FILTER, FILLED TRANSMISSION. RAN TRUCK AND TESTED TRANSMISSION, ALL TESTED GOOD.	REPAIR TRANSMISSION		\$4,952.74
004	9/14/2021 13:48	1255	13874 Hours	203668 Miles	CAD SYSTEM FEED CHAIN AND GEAR WORN, DISASSEMBLED AND REPLACED CHAIN AND GEAR, ADJUSTED AND CHECKED	REPAIR CAD FEED PULLEY		\$75.00
004	9/10/2021 8:59	1258	13856 Hours	203049 Miles		REPAIR AIR LEAK	Found Ds front axle rear air bag leaking. Removed old air bag, installed new air bag, and reconnected air line. Aired up truck to check for additional leaks. No additional leaks were found. Bag was replaced at 13856 hrs.	\$188.85
004	8/6/2021 11:55	1229	12767 Hours	186020 Miles	REPLACED AIR DRYER CART. AND REPLACED PURGE KIT. TESTED BATTERIES AND REPAIRED WIRING TO BATTERY MAINTAINER	SERVICE AIR DRYER		\$244.00
004	8/6/2021 11:55	1229	12767 Hours	186020 Miles	DISCONNECTED AND REMOVED MAIN FEED BELT, INSTALLED FEED BELT AND CONNECTED, INSTALLED ACCY, CONNECTED TO FEED BELT. CHECKED OPERATION AND ADJUSTED BELT.	REPLACE CAD SYSTEM MAIN FEED BELT		\$296.00
004	8/5/2021 13:03	1220	12767 Hours	186020 Miles	PERFORMED 250HR SERVICE PER CHECKLIST, ENGINE OIL AND FILTER, FUEL FILTERS AND HYD FILTER, GREASED CHASSIS.	250 HR service and repairs		\$207.64
004	7/26/2021 9:25	1190	12767 Hours	186020 Miles	U-JOINT ON MAIN DRIVESHAFT LOOSE, REMOVED AND INSTALLED NEW U-JOINT, GREASED U-JOINT.	Drivetrain		\$99.75

004	7/26/2021 9:25	1190	12767 Hours	186020 Miles	PERFORMED PM SERVICE, CHANGED ENGINE OIL AND FILTER, CHANGED FUEL FILTERS AND GREASED CHASSIS, CHECKED ALL OIL BOXES AND AIR FILTER	250 HR service and repairs		\$93.24
004	7/26/2021 9:25	1190	12767 Hours	186020 Miles	PASSENGER SIDE AIR TANK STRAP BROKEN, CLEANED AND WELDED STRAP TOGETHER AND SECURED AIR TANK.	Air System		\$60.00
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		Drivetrain	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$486.20
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		125 HR PM Inspection	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$94.00
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles	Drain differentials and transmissions and change fluid	Drivetrain	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$311.33
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		Hydraulics	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$40.00
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles	Service air dryer	Air System	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$48.00
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		Inspection	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$70.00

004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		Brakes	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$255.90
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles	install battery maintainer and check block heater	Electrical	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$68.18
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles	Replace all bad lights	Electrical	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$91.80
004	4/20/2021 9:24	1156	12767 Hours	186020 Miles		Suspension	Inspected truck found that all shocks on drive axle are bad, replaced shocks, and mudflaps. Also replaced oils in differentials and transmission, found that input shaft threads on front differential are stripped. Removed front differential, Removed input shaft, replaced bearings, race and resealed and reassembled. Sent samples off for testing. Found front drive axle slack adjusters are bad Replaced slack adjusters. Serviced air dryer and replaced all lights.; Fluids changed at 1286hr	\$387.80
004	2/5/2021 19:26	1153	12767 Hours	186020 Miles		Cab		\$0.00
004	12/14/2020 21:14	1113	12708 Hours	184257 Miles		Drivetrain	Drained oil, greased chassis, checked boxes. Replaced oil filter, fuel filter, and cleaned air filter. Oil change performed at 12708 HR. Filters used, 1792, 3674.; Removed rear differential, removed axles, and removed wheels, brakes and hubs. Found driverside axle lock axle bad, and wheel bearings bad on rear drive axle. Cleaned out differential housing, installed new differential. Drove out old races, installed new races, bearings, and wheel seal.; Reinstalled hubs, brakes, drums, and axles. Reinstalled drive line. Removed drivelines, removed final drive. Removed bearings, and disassembled final drive. Installed new clutch, bearings, and reassembled final drive. Reinstalled final drive and drivelines	\$3,138.02

004	12/14/2020 21:14	1113	12708 Hours	184257 Miles		CAD	Drained oil, greased chassis, checked boxes. Replaced oil filter, fuel filter, and cleaned air filter. Oil change performed at 12708 HR. Filters used, 1792, 3674.; Removed rear differential, removed axles, and removed wheels, brakes and hubs. Found driverside axle lock axle bad, and wheel bearings bad on rear drive axle. Cleaned out differential housing, installed new differential. Drove out old races, installed new races, bearings, and wheel seal.; Reinstalled hubs, brakes, drums, and axles. Reinstalled drive line. Removed drivelines, removed final drive. Removed bearings, and disassembled final drive. Installed new clutch, bearings, and reassembled final drive. Reinstalled final drive and drivelines.	\$5,635.78
004	12/14/2020 21:14	1113	12708 Hours	184257 Miles		250 HR service and repairs	Drained oil, greased chassis, checked boxes. Replaced oil filter, fuel filter, and cleaned air filter. Oil change performed at 12708 HR. Filters used, 1792, 3674.; Removed rear differential, removed axles, and removed wheels, brakes and hubs. Found driverside axle lock axle bad, and wheel bearings bad on rear drive axle. Cleaned out differential housing, installed new differential. Drove out old races, installed new races, bearings, and wheel seal.; Reinstalled hubs, brakes, drums, and axles. Reinstalled drive line. Removed drivelines, removed final drive. Removed bearings, and disassembled final drive. Installed new clutch, bearings, and reassembled final drive. Reinstalled final drive and drivelines.	\$173.22
004	11/3/2020 9:37	1097	12582 Hours	182822 Miles		Replace windshield		\$160.00
004	11/3/2020 9:32	1088	12582 Hours	182822 Miles		Hydraulics	replaced blown inlet hose.	\$64.00
004	11/3/2020 9:30	1096	12582 Hours	182822 Miles		Drivetrain	Had to make new clutch linkage, to adjust clutch brake. Adjusted clutch	\$100.81
004	11/3/2020 9:11	1095	12582 Hours	182822 Miles		125 HR PM Inspection	Performed inspection, Found driver side wiper not working, Found two top cab lights inop, found rear box light inop. Repaired lights, installed nut onto wiper arm because it was missing. Found hydraulic tank leaking, tightened drain plug, but also identified that return line fittings are leaking. Found that differential lock indicator on diff was unplugged. Cleaned	\$72.00
004	9/18/2020 8:49	1032	0 Hours	0 Miles		Electrical	Removed old starter, Installed new starter. Reconnected batteries, and tested. Truck starts good.	\$364.50
004	8/25/2020 16:25	1015	0 Hours	0 Miles		CAD	Installed new pivot shaft. Installed new pivot motor, and gear	\$0.00
004	8/25/2020 15:52	1016	0 Hours	0 Miles		Service	Performed service at 12144 HR. Changed oil filter, fuel filter, air filter, and replaced oil. Greased chassis, and checked all boxes.; Removed and resealed front differential.	\$0.00
004	8/25/2020 15:52	1016	0 Hours	0 Miles		Drivetrain	Performed service at 12144 HR. Changed oil filter, fuel filter, air filter, and replaced oil. Greased chassis, and checked all boxes.; Removed and resealed front differential.	\$0.00